


6



Horizontal



保持力の調整(水平時)



Press down the arm to a horizontal position

S=5mm
Allen key
CS=5mm
Allen key

Be sure to keep the arm in horizontal position during adjustment. Or else, it would be difficult to adjust the mount.

1 turn \approx 1 lbs \approx 0.4kg

NOTE: Turn clockwise to reduce tension for lighter monitors and counter-clockwise to increase tension for heavier monitors.

7

モニター角度の調整



Adjust the damp for tilting.
Turn counter-clockwise to reduce damping and clockwise to increase damping.S=5mm
Allen key
C

Cable cover

F

S=5mm
Allen key

-90°/+85° tilt

① ツメを
差込む





② 押込む

Insert cables into cable covers.
Leave enough space at arm
joints for full adjustment.

ケーブルカバー装着



Gas Spring Aluminum LCD Monitor Desk Mount



MA-GS105BK 組立説明書

Installation


INSTRUCTIONS

Warning

- ⚠ Prior to the installation of this product, the installation instruction must be read and completely understood. Failure to do so may result in personal injury, property damage or voiding of factory warranty.
- ⚠ Do not install on a structure that is prone to vibration, movement or chance of impact. Reinforce the structure as required before installation.
- ⚠ The desk clamp can support a maximum thickness of 9 cm. Confirm the desk edge before installation.
- ⚠ Pay attention to the weight capacity of the mount. Exceeding the limitation can result in function unworkable or even serious personal injury and property damage.
- ⚠ Never operate the mount if parts are missing or damaged. Contact your local service center for warranty service.


PRODUCT LINE GRAPH

可動範囲図




OR

Recessed Surface Installation




- ① Put spacers on screws.
Install the upper two screws and don't screw them tightly.




背面が凹み型モニターの場合、
スペンサーをご使用下さい

- ② Leave some space and hang the monitor on the head plate.




- ③ Install the lower two screws and fasten the upper two screws.



5 Flush Surface Installation


M4x12 (x4)
Screws
A

- ① Install the upper two screws and don't screw them tightly.




背面が平型モニターの場合、
短いネジをご使用下さい

- ② Leave some space and hang the monitor on the head plate.



- ③ Install the lower two screws and fasten the upper two screws.













TOOLS REQUIRED NOT INCLUDED



プラス“+”ドライバー
別途ご用意して下さい


PARTS INCLUDED



A	 M4x12 (x4) Screws	 M4x30 (x4) Screws
B	 12x5.8x16 (x4) Spacer	
C	 S=4mm (x1) Allen key	 S=5mm (x1) Allen key
D	 M6x12 (x3) Screws	
E	 Pad big (x1)	 Pad small (x1)
F	 Cable cover(x1)	

1 ご注意：ケーブルバンドをゆっくり外して下さい


Tear off the cable tie and rebound carefully.




Desk Clamp installation

クランプ固定の場合

2



3



Grommet installation

グロメット固定の場合

4

